



CERT

DIN-DVGW type examination certificate

DIN-DVGW-Baumusterprüfzertifikat

NG-4390AL0030

Registration Number
Registriernummer

Field of Application <i>Anwendungsbereich</i>	products of gas supply <i>Produkte der Gasversorgung</i>
Owner of Certificate <i>Zertifikatinhaber</i>	WITT GmbH & Co. Holding & Handels KG Salinger Feld 4-8, D-58454 Witten
Distributor <i>Vertreiber</i>	WITT-Gasetechnik GmbH & Co. Produktions- und Vertriebs KG Salinger Feld 4-8, D-58454 Witten
Product Category <i>Produktart</i>	gas fittings: Gas back flow safety device (4390)
Product Description <i>Produktbezeichnung</i>	Gas back flow safety device without flame arrestor
Model <i>Modell</i>	338
Test Reports <i>Prüfberichte</i>	laboratory control test: 19033490-I from 10.09.2019 (BAG) type testing: 2-559/2011 from 11.04.2011 (BAG)
Test Basis <i>Prüfgrundlagen</i>	DIN 8521-2 (01.08.1993)

Date of Expiry / File No. 31.12.2025 / 20-0830-GNV
Ablaufdatum / Aktenzeichen



05.02.2021 Rie A-1/2

Date, Issued by, Sheet, Head of Certification Body
Datum, Bearbeiter, Blatt, Leiter der Zertifizierungsstelle

DVGW CERT GmbH is an accredited body by DAkkS according to DIN EN ISO/IEC 17065:2013 for certification of products for energy and water supply industry.

DVGW CERT GmbH ist von der DAkkS nach DIN EN ISO/IEC 17065:2013 akkreditierte Stelle für die Zertifizierung von Produkten der Energie- und Wasserversorgung.



Deutsche
Akkreditierungsstelle
D-ZE-16028-01-05

DVGW CERT GmbH
Zertifizierungsstelle

Josef-Wirmer-Str. 1-3
53123 Bonn

Tel. +49 228 91 88 - 888
Fax +49 228 91 88 - 993

www.dvgw-cert.com
info@dvgw-cert.com

Type	Technical Data	Remarks
<i>Typ</i>	<i>Technische Daten</i>	<i>Bemerkungen</i>
338	maximum operation pressure: 0,1 bar	

Hints of Utilization / Remarks***Verwendungshinweise / Bemerkungen***

The gas back flow safety device is to use only in connection with an additional safety device, which interrupts the further gas feed in case of a flash back.

After each flash back the gas back flow safety device is to be exchanged or to be checked regarding correct function mode before re-installation.